



1 Manta filtrante o pré-filtrado G3-G4



2 Filtro de flujo laminar H13-H14



3 Filtro HEPA de alto caudal H13-H14



4 Filtro de bolsas compact al menos F5